



ON SITE ... INSPECTIONS

750 Industrial Ave. Wellington OH 44090

800-326-0406



This **CONFIDENTIAL INSPECTION REPORT** is the exclusive property of **ON SITE INSPECTIONS** and the client whose name appears herein. This report may not be reproduced without the written consent of **ON SITE INSPECTIONS**.

© 2004 ON SITE INSPECTIONS

AREA - ATTIC



PICTURE 2 - north attic attach job---hole

AREA - DECK PORCH



PICTURE 10 - south porch off pillar



PICTURE 11 - south porch possibly supported by sistern

AREA - EXTERIOR



PICTURE 12 - crack in north chimney



PICTURE 13 - rotted wood between north porch and house

AREA - con't



PICTURE 7 - area between north porch and house



PICTURE 8 - foundation brick needs tuck pointing

AREA - con't



PICTURE 9 - brick work on foundation

AREA - PLUMBING SERVICE



PICTURE 1 - sanitary discharge with duct tape

AREA - ROOF



PICTURE 3 - main roof chimney--brick



PICTURE 4 - north chimney brick

AREA - con't



PICTURE 5 - late comig off



PICTURE 6 - flashing on main chimney